

Jate of Utah DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

Supervisor



October 7, 2005

Mine Name: Dry Creek Mine

Operator Name: All Gypsum Corporation

John Fain

4388 North Bulldog Road Cedar City, Utah 84720

Inspector(s): Doug Jensen Other Participants: None Mine Status: Inactive **Permit number:** S/021/026 **Inspection Date:** Sept. 27, 2005

Time: 2:00 PM

Weather: Warm, Breezy

Elements of Inspection Evaluated Enforcement Comment 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality

Purpose of Inspection:

12. Other

This site had not been visited since 1999. I inspected the site while I was in the area to document any changes that may have occurred since that time.

Inspection Summary:

The disturbance at the site remains unchanged but volunteer vegetation has came in nicely on the flat areas.

This site had not been GPS'd, I walked the area to in order to map the total disturbance at the site to document the permit area. The GPS mapping indicates that the total disturbance at the site is 2.8 acres; the map is attached to this report.

I did not have a camera at the time of this visit; therefore; no pictures were taken. I will visit the site in the future to photo-document the area.

Conclusions and Recommendations:

The site has remained stable with no environmental concerns noted. I will continue to monitor the site when in the area.

Inspector's Signature	though bean	Date: October 7, 2005	

DJ:jb

cc:

Jim Fain, Operator Attachment: GPS map

O:\M021-Iron\S0210026-DryCreekMine\inspections\nsp-09272005i.doc

Utah!
Where ideas connect™


S210026 DRY CREEK MINE

Mine Name: Dry Creek Mine Township 36 S Range 10 W Section 18 SLBM Mine Number: M0210026

Inspection Date Sept. 27, 2005 Map Produced by DKS 0 0 0 0000 Acres Disturbed Acres Regraded Acres Seeded Road Acres Disturbed Total Acres Distrubed Acres Released Acres Excluded Acres PreExisting

Acres Prelaw

Legend
All items symbolized in legend may not be appear on map ==: Main Dirt Road





1:7,500 1 inch equals 625 feet

Different data sources and input scales may cause misaligment of data layers. This product may not meet DOGM standards for accuracy and content. Verify Scale